## EXHIBIT A TO OFFER TO PURCHASE -- CITY OF MILWAUKEE SCOPE OF WORK

4730 North 31st Street

Scope of Work for Property Located at:

Other

	Property is: Single Famil	y ☑	Duple	☐ Other ☐			
Date:	10/11/2018	<u> </u>		OCCUPIED VACANT	]		
				se. City does not warrant content or conclusions, and is not	responsible t	for errors,	
	discovery of conditions that are or n	•					
				te Essential Repairs and obtain "Essen			
and prov		180 day	ys of C	ty's deed to buyer in order to get returr	1 of perio	ormance de	posit.
Location Entire	Required Work			Note/Comments		Cost	
Building	Structural Violations	n/a □	Yes [		\$		
	Defective/Missing HVAC	n/a 🗆	Yes [		\$		
	Defective/Missing Plumbing	n/a 🔲	Yes ⊡	make basement bath code compliant or remove	\$ \$	1,220.00	
	Defective/Missing Electrical	n/a 🔲	Yes ⊡	Protect & repair all NM wiring, per code. Permit required.	\$	1,400.00	
	Defective/Missing Egress	n/a 🔲	Yes [		\$		
	Defective/Missing Smoke Alarm	n/a 🔲	Yes [		\$		
	Defective/Missing CO Alarm	n/a 🔲	Yes [		\$		
	Defective/Missing Roof (Major)	n/a 🔲	Yes [		\$		
	Missing Window(s)	n/a 🗆	Yes [		\$		
	W : 5. : 5 ()	, $\square$	, c		•	E	ssential Repairs
	Missing Exterior Door(s)	n/a	Yes		\$	2 222 22	Total
	Other	n/a 🗌	Yes [√		\$	3,600.00	6,220.00
				notified that the following are code vio			
must be a	addressed and are subje	ט סז זספ	epartn	ent of Neighborhood Services (DNS) er	norceme	ent.	
Exterior (	Condition Report						
Location	Required Work	, _	v =	Note/Comments	•	Cost	
Site	Landscaping	n/a ∐	Yes ☑	•	\$	400.00	
	Steps/Handrails	n/a ∐	Yes 🗹		\$	1,000.00	
	Service walks	n/a 🗌	Yes ⊡		\$	1,200.00	
	Fencing	n/a 🗌	Yes ☑	Including gate	\$	700.00	
	Parking	n/a 🗌	Yes ⊡	SEE ESSENTIAL REPAIRS	\$		
	Retaining walls	n/a 🗌	Yes [		\$		
	Other	n/a 🔲	Yes [		\$		
	Other	n/a 🔲	Yes [		\$		
Garage	Singles: repair	n/a 🗌	Yes [		\$		
	Shingles: Roof over existing	n/a 🗌	Yes [		\$		
	Shingles:Tear off & re-roof	n/a 🗌	Yes [		\$		
	Gutters/downspouts	n/a 🗌			\$		
	Flashing	n/a 🗌	Yes [		\$		
	Eaves	n/a 🗌	Yes [		\$		
	Siding	n/a 🗌	Yes [		\$		
	Ciding	18 L	1C3 L		ΨΨ		
	Doors	n/o 🗆	Voc F		Φ		
	Doors	n/a 🗌	Yes [		\$		
	Windows	n/a 🗌	Yes [		\$		
	Windows Slab	n/a 🗌	Yes [		\$		
	Windows	n/a 🗌	Yes [		\$		

\$

n/a Yes

## Porches

House

Roof	n/a Yes	\$	
Deck-upper	n/a Yes	\$	
Decklower	n/a Yes	\$	
Steps/handrails	n/a Yes	\$	
Ceiling	n/a Yes	\$	
Guardrails	n/a Yes V Front and rear; includes handrails	\$	00.00
Structural	n/a Yes	\$	
Paint	n/a Yes	\$	
Other	n/a 🗌 Yes 🗌	\$	
Chimney	n/a ☐ Yes ☑	\$	500.00
Shingles: repair	n/a 🗌 Yes 🗎	\$	
Shingles: Roof over existing	n/a 🗌 Yes 🗎	\$	
Shingles:Tear off & re-roof	n/a  Yes	\$	
Gutters/downspouts	n/a Yes 🗹 Including cleaning	\$ 1,2	208.00
Flashing	n/a  Yes	\$	
Eaves	n/a  Yes	\$	
Siding	n/a ☐ Yes ☑	\$ 1,2	200.00
Storm Doors	n/a  Yes 🗹	\$ 2	265.00
Prime ("main") Doors	n/a 🗌 Yes 🗌	\$	
Storm Windows	n/a ☐ Yes ☑	\$ 1	98.00
Prime ("main") Windows	n/a ☐ Yes ☑	\$	800.00
Paint	n/a ☐ Yes ☑	\$ 3,6	00.00
Foundation	n/a 🗌 Yes 🗌	\$	
Electrical	n/a 🗌 Yes 🗌	\$	
Window Screens	n/a ☐ Yes ☑	\$	750.00
Address tiles on back of house	n/a ☐ Yes ☑	\$	25.00
Other	n/a  Yes _	\$	
Other	n/a Yes	\$	

<sup>\*</sup>average contracted cost. Actual costs may vary. Self help will reduce the amount.

18,966.00

Exterior: Estimated Cost:\*

Interior Co	ondition Report							
	Unit: Entire unit (single family) Upper unit of duplex	✓ □			Lower unit of duplex Other			
	Required Work							
Heating	Repair/replace boiler	n/a 🗌	Yes [					\$
	Repair radiation	n/a 🗌	Yes [		-			\$
	Repair/replace furnace	n/a 🔲	Yes [					\$
	Repair ductwork	n/a 🗌	Yes [					\$
	Replace thermostat	n/a 🔲	Yes [					\$
	Repair/replace grilles	n/a 🗌	Yes [	<b>✓</b>				\$ 200.00
	Tune boiler/furn. insp ht exchanger	r n/a 🔲	Yes [					\$
Electrical	Repair/replace receptacles	n/a 🗌	Yes [	7				\$
	Repair/replace switches	n/a 🗆						\$
	Repair/replace fixtures	n/a 🗌						\$
	Install outlets and circuits	n/a 🔲	Yes [					\$
	Install outlets and circuits	n/a 🔲	Yes [					\$
	Install outlets and circuits	n/a 🔲	Yes [					\$
	Install outlets and circuits	n/a 🔲	Yes [					\$
	Upgrade service	n/a 🔲	Yes [					\$
	Misc violations	n/a 🔲	Yes [	<b>✓</b>	SEE ESSENTIAL R	EPAIRS		\$
	Other	n/a 🔲	Yes [	<b>✓</b>	Provide access to p	oanel, per	code.	\$
Plumbing	Repair/replace kitchen sink	n/a 🗌	Yes [					\$
	Repair/replace kitchen sink faucet		Yes [					\$ 
	Repair/replace tub	n/a 🗌						\$ 
	Repair/replace tub faucet	n/a 🗌						\$
	Repair/replace toilet	n/a 🗌	Yes [	<u></u>				\$
	Repair/replace lavatory	n/a 🗌		<u> </u>	SEE ESSENTIAL R	EPAIRS		\$ 
	Repair/replace lavatory faucet	n/a 🗌	Yes [	 _				\$
	Repair/replace wash tub	n/a 🗌	Yes [	_				\$
	Repair/replace wash tub faucet	n/a 🗌						\$
	Unclog piping:	n/a $\square$						\$
	Repair drain/waste/vent piping	n/a $\square$	Yes [					\$
	Repair water piping	n/a 🗌	Yes [		_			\$
	Repair/replace water heater	n/a 🗌	Yes [					\$
	Dryer venting	n/a 🗌	Yes [					\$ 50.00
	Rasement hathroom	n/a	Vac F	<u>ار</u>	SEE ESSENTIAL R	FPAIRS		\$ 

Windows							
	Replace broken glass	n/a 🔲	Yes		-	\$	
	Repair or replace sash	n/a □	Yes			\$	
Doors							
	Repair or replace doors	n/a 🔲	Yes	✓	Including defective door(s) and double dead-bolt egress violation	\$	245.00
	Repair or repl. locks/latches	n/a 🔲	Yes		Self Help	\$	
Walls/Ceilin	gs						
	Repair or repl. @ defective	n/a 🔲	Yes	✓	_	\$	1,600.00
Paint							
	Repair or repl. @ defective	n/a 🔲	Yes			\$	800.00
Fire Safety							
•	Install smoke/CO alarm:bsmt.	n/a 🔲	Yes		Self Help	\$	
	Install smoke/CO alarm: 1st flr.	n/a 🔲	Yes		Self Help	\$	
	Install smoke/CO alarm: 2nd flr.	n/a 🔲	Yes		Self Help	\$	
Handrails	Repair/replace defective	n/a □	Yes	V	Self Help (basement)	\$	100.00
Stairs		<u> </u>					
Floors	Repair defective	n/a 🔲	Yes			\$	
110015	Repair defective	n/a □	Yes	П		\$	
Other					-	<u> </u>	
		n/a 🗌	Yes			\$	
		n/a 🔲	Yes			\$	
		n/a 🔲	Yes			\$	
		n/a 🔲	Yes			\$	
					Interior: Estimated Cost:	\$	2,995.00
					Total Exterior and Interior Cost:*	\$	21,961.00
							•

Inspected by: Inspector Gorski Date: 10/11/2018

## Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

## **Important Information Regarding Permits**

 $\label{eq:local_equation} \mbox{All plumbing, heating, electrical, and structural repairs require permits before work can start.}$ 

Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located at 7630 W. Mill Road.

 $<sup>\</sup>mbox{^*}\mbox{average}$  contracted cost. Actual costs may vary. Self help will reduce the amount.